

OCT 7 1981



Victoreen, Incorporated
ATTN: Mr. D. M. Mayhew
President
10101 Woodland Avenue
Cleveland, Ohio 44104

License No. 34-00486-04
License No. 34-00486-05
License No. 34-00486-09

Gentlemen:

This refers to the routine safety inspection conducted by Mr. D. R. Gibbons of this office on September 22, 1981, of activities authorized by NRC Byproduct Material Licenses No. 34-00486-04, No. 34-00486-05 and No. 34-00486-09 and to the discussion of our findings with Mr. Stanley Kawecki at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as specified in enclosed Appendix A. A written response, submitted under oath or affirmation, is required.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Robert E. Burgin
D. J. Sreniawski, Chief
Materials Radiation Protection
Section 2

Enclosure: Appendix A,
Notice of Violation

cc w/encl:
DMB/Document *[redacted]* k (RIDS)

RIII
[Signature]
Gibbons/so
10/2/81

RIII
[Signature]
Wiedeman

RIII
[Signature]
Sreniawski
10/5

IE07
S/1

8110150266 811007
NMS LIC30
34-00486-04 PDR