

October 5, 1981

PRN-LI-81-446

Mr. James P. O'Reilly, Director, Region II  
Office of Inspection and Enforcement  
U.S. Nuclear Regulatory Commission  
101 Marietta Street, Suite 3100  
Atlanta, Georgia 30303




Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 251-81-10  
TURKEY POINT UNIT 4  
DATE OF OCCURRENCE: SEPTEMBER 3, 1981  
TECHNICAL SPECIFICATION 3.8.1.b.1  
"A" AUXILIARY FEEDWATER PUMP

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30 day notification of the subject occurrence.

Very truly yours,

  
J.W. Williams, Jr.  
Director  
Nuclear Energy

PLP/mbd

Attachment

cc: Director, Office of Inspection and Enforcement (30)  
Harold F. Reis, Esquire  
File 933.1 TP

IE22  
5  
1/1