TENNESSEE VALLEY AUTHORITY


CHATTANOOGA, TENNESSEE 37401 .

1750 Chestnut Street Tower II

October 5, 1981

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:



The enclosed report provides details concerning TI-64-55A (torus temperature) which was observed to have an erroneous indication. This report is submitted in accordance with Browns Ferry unit 3 Technical Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

ector of Nuclear Power

Enclosure (3) cc (Enclosure):

> Office of Management Information and Program Control U.S. Nuclear Regulatory Commission Washington, DC 20555

Director (40) Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

Mr. Bill Lavallee Nuclear Safety Analysis Center Palo Alto, California 94303

Mr. R. F. Sullivan, NRC Inspector, Browns Ferry

and the control of th