



DESIGNATED ORIGINAL

Certified By John R. Hanson, R-III

Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

DMB/LER

October 12, 1981

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137PRAIRIE ISLAND NUCLEAR GENERATING PLANT
Docket No. 50-282 License No. DPR-42Tube Degradation in Unit No. 1 Steam GeneratorsThe Licensee Event Report and supplement for this event is attached.
Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.1.c since it represents steam generator tube degradation. Additional information will be provided in our Inservice Inspection Summary report which will be submitted following the current refueling outage.

L O Mayer, PE
Manager of Nuclear Support Services

LOM/DMM/bd

cc: Director, IE, USNRC (40)
Director, MIPC, USNRC (3)
NRC Resident Inspector
MPCA
Attn: J W FermanIE22
S/18110200593 811012
PDR ADOCK 05000282
S PDR

OCT 14 1981