


*Southern California Edison Company*




P. O. BOX 800  
2244 WALNUT GROVE AVENUE  
ROSEMEAD, CALIFORNIA 91770

J. M. CERRAN  
MANAGER, QUALITY ASSURANCE

TELEPHONE  
(213) 572-1895

October 7, 1981

Mr. R. H. Engelken, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission  
Region V  
Suite 202, Walnut Creek Plaza  
1990 North California Boulevard  
Walnut Creek, California 94506



Dear Mr. Engelken:

Subject: Docket Nos. 50-361 and 50-362  
San Onofre Nuclear Generating Station, Units 2 & 3

This letter confirms verbal notification on October 6, 1981 of a condition discovered in construction which is considered potentially reportable in accordance with 10CFR50.55(e). The condition involves malfunction of Pressurizer Level Indicators due to collection of condensate in low points of flexible interconnecting tubing.

We are performing an evaluation of this condition and will submit an appropriate report in accordance with 10CFR50.55(e)(3) if the condition is determined to be reportable. If you have any questions or require additional information, please let me know...

Very truly yours,

*J. M. Cerran*

cc: A. Chaffee (NRC, San Onofre Units 2 & 3)  
Dr. L. T. Papay

REGIONAL

1981 OCT 19 PM 12:54

RECEIVED  
NRC

8110270148 811007  
PDR ADOCK 05000361  
S PDR

81-175