



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

October 20, 1981

D. L. ASWELL
Vice President-Power Production

W3K-81-0386

Q-3-A? .02.01

Q-3-A35:07.17

Mr. K. V. Seyfrit, Director, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



SUBJECT: Waterford SES Unit 3
Significant Construction Deficiency #17
"Base Metal Defect in Main Steam and Feedwater
Containment Penetration Anchors"
Third Interim Report

Reference: 1) Interim Report W3K81-0095 dated 2/27/81
2) Telecon to L. Martin (NRC) from L. L. Bass (LP&L)
dated 10/19/81

Dear Mr. Seyfrit:

In the referenced interim report (1), LP&L committed to submit a final report on Significant Construction Deficiency #17 by October 31, 1981.

The extent of repairs necessary to complete the corrective action on this deficiency has made it impossible to meet this deadline.

A final report on this item will be submitted by January 29, 1982.

If there are any questions, please let us know.

Very truly yours,

D. L. Aswell

DLA/LLB/grf

cc: 1) Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8110270325 811020
PDR ADDCK 05000382
S PDR

IF 27
5/10