


USNRC REGION II
ATLANTA, GEORGIA

Duke Power Company

McGUIRE NUCLEAR STATION

INCIDENT INVESTIGATION REPORT FORM

Att: P. Kellogg



Incident Investigation Report Number: 81-229 Date: 10/29/81

Unit: 1 Time/Date of Incident: 10/8/81 Time/Date of Discovery: 11/28/81

Unit Status of Time of Incident: N/A

Description of Incident: Forty-eight feet of SA/A 193 Gr. B & 3/4" stud material and 102 SA/A 194 Gr. B nuts purchased for use on the KF steamers in the spent fuel are missing. According to CP 357 Rev 5 the studs and nuts that are lost can be

Method of Discovery: used in for any data base class piping application

Immediate Corrective Action: Design and Construction are investigating the possible ramifications of the situation

Reportable Pursuant to Technical Specifications: N/A

Time/Date Reported to Station Manager: 10/29/81

Time/Date Reported to General Office: 11/29/81

Time/Date Reported to NRC/OIE Region II: 11/15 10/29/81

NRC Inspector Notified: P. Kellogg

Type of Incident: ✓ 10 Day RO 21 Day RC Other

Investigator Assigned: Design Engineering

Report Due to SRC On: N/A Report Due to G.O. Licensing On: N/A

Report Due to NRC On: 11/19/81

Time/Date Telecopied or Otherwise Transmitted: 1230 10/29/81

Prepared By: P.D. Langh Phone: 875-1357

Reviewed By: Station Manager Approval:

8111050501 811029
PDR ADOCK 05000369
PDR

REGIONAL DIRECTOR
DEPUTY DIRECTOR
ASSISTANT TO DIRECTOR
DIRECTOR, RRPI
DIRECTOR, EPOS
DIRECTOR, ENF/INV
DIRECTOR, ETI
PUBLIC AFFAIRS OFFICER