

**Detroit
Edison**

Donald A. Wells
Manager Quality Assurance
(313) 237-9657
2000 Second Avenue
Detroit, Michigan 48226
(313) 237-8000

September 28, 1981
EF2-54149

Mr. R.L. Spessard
Reactor Construction and Engineering
Support Branch
U.S. Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Reference: Letter EF2-54141 from Mr. Donald A. Wells to Mr. G. Fiorelli
Dated August 20, 1981

Subject: Noncompliance at Enrico Fermi Unit 2 Construction Site

Dear Mr. Spessard:


This letter completes our response to the item of noncompliance contained in your IE Report 50-341/81-07. It supplements information on the same subject submitted in our letter of August 20, 1981 (reference). This inspection of Enrico Fermi Unit 2 Site Construction activities was performed by Mr. K.D. Ward of NRC Region III on June 16-19, 1981.

Only the cited item of noncompliance is discussed in this reply as required by Section 2.201 of the NRC's "Rules of Practice", Part 2, Title 10, Code of Federal Regulations.

The enclosed response is arranged in sequence of items cited in the body of your report and the finding and section numbers are referenced as applicable.

We trust this letter satisfactorily answers the concerns raised in your report. We will be glad to discuss any further concerns you might have.

Very truly yours,



DAW/HAW/cp

8111060658 811002
PDR ADOCK 05000341
Q PDR

OCT 8 1981

Mr. R. L. Spessard
Page Two

September 30, 1981
EF2-54149

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
Division of Reactor Inspection Programs
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Mr. Bruce Little, Resident Inspector
U.S. Nuclear Regulatory Commission
Resident Inspectors Office
6450 North Dixie Highway
Newport, Michigan 48166