


**LOUISIANA
POWER & LIGHT**

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

D. L. ASWELL
Vice President-Power Production



W3K81-0397
Q-3-A35.02.01
Q-3-A35.07

Mr. K. V. Seyfrit, Director, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit 3
Potential Construction Deficiency #54
"Repetitive Failures of Limitorque Operator"
Third Interim Report

Reference: Telecon to L. Martin (NRC) from L. I. Bass (LP&L)
dated October 29, 1981

Dear Mr. Seyfrit:

The subject item report was due to the NRC on October 30, 1981. A satisfactory response has not been received from the vendor, Anchor/Darling; therefore, Ebasco has not completed the engineering evaluation. This delay has been caused by Anchor/Darling's transfer of their records from California to Pennsylvania.

A report on this item will be submitted to the NRC on or before December 30, 1981.

If you have any questions, please let me know.

Very truly yours,

D. L. Aswell

DLA/LLB/ncd

8111090718 811106
PDR ADDCK 05000382
S PDR

- cc: 1) Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

IE 27
5/18