

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | N | Y | J | A | F | I | 2 | 0 | 0 | - | 0 | 0 | 0 | 0 | - | 0 | 0 | 0 | 3 | 4 | 1 | 1 | 1 | 1 | 4 | _____ | 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 31 CAT 56

CON'T
0 1 | REPORT SOURCE | L | 6 | 0 | 5 | 0 | 0 | 0 | 3 | 3 | 3 | 7 | 1 | 0 | 0 | 6 | 8 | 1 | 3 | 1 | 0 | 2 | 3 | 8 | 1 | 9
7 8 9 DOCKET NUMBER 60 61 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During normal operation, while conducting surveillance to satisfy TS Table 4.2-2,
0 3 | HPCI turbine exhaust diaphragm pressure switch 23-PS-86B was found set at 10.7 psig
0 4 | when required by TS Table 3.2-2, Item 33, to be set equal to or less than 10.0 psig.
0 5 | The redundant channel was satisfactory. No significant hazard existed.
0 6 | _____
0 7 | _____
0 8 | _____

0 9 | SYSTEM CODE | S | F | 11 | CAUSE CODE | E | 12 | CAUSE SUBCODE | E | 13 | COMPONENT CODE | I | N | S | T | R | U | 14 | COMP. SUBCODE | S | 15 | VALVE SUBCODE | Z | 16 |
7 8 9 9 10 11 12 13 14 15 16 17 18 19 20

17 | LER NO REPORT NUMBER | 8 | 1 | 21 | 22 | SEQUENTIAL REPORT NO. | 0 | 7 | 2 | 24 | 26 | OCCURRENCE CODE | 0 | 3 | 28 | 29 | REPORT TYPE | L | 30 | REVISION NO. | 0 | 32 |
23 | 24 | 26 | 27 | 28 | 29 | 30 | 31 | 32

ACTION TAKEN | E | 18 | FUTURE ACTION | Z | 19 | EFFECT ON PLANT | Z | 20 | SHUTDOWN METHOD | Z | 21 | HOURS | 0 | 0 | 0 | 0 | 37 | 40 | ATTACHMENT SUBMITTED | N | 23 | NPD-4 FORM SUB. | N | 24 | PRIME COMP SUPPLIER | N | 25 | COMPONENT MANUFACTURER | B | 0 | 6 | 9 | 26
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Instrument drift was the cause. The instrument was immediately calibrated and
1 1 | surveillance has been increased to once each week until satisfactory performance is
1 2 | demonstrated. No additional action is required.
1 3 | _____
1 4 | _____

1 5 | FACILITY STATUS | E | 28 | % POWER | 0 | 7 | 0 | 29 | OTHER STATUS | NA | 30 | METHOD OF DISCOVERY | B | 31 | DISCOVERY DESCRIPTION | Surveillance | 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 6 | ACTIVITY CONTENT RELEASED OF RELEASE | Z | 33 | AMOUNT OF ACTIVITY | NA | 35 | LOCATION OF RELEASE | NA | 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 7 | PERSONNEL EXPOSURES NUMBER | 0 | 0 | 0 | 37 | TYPE | Z | 38 | DESCRIPTION | NA | 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 8 | PERSONNEL INJURIES NUMBER | 0 | 0 | 0 | 40 | DESCRIPTION | NA | 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

1 9 | LOSS OF OR DAMAGE TO FACILITY TYPE | Z | 42 | DESCRIPTION | NA | 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

2 0 | PUBLICITY ISSUED DESCRIPTION | N | 44 | DESCRIPTION | NA | 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32

B111100784 811023
PDR ADOCK 05000333
S PDR

NRC USE ONLY

NAME OF PREPARER W. Verne Childs PHONE 315-342-3840