

TENNESSEE VALLEY AUTHORITY


CHATTANOOGA, TENNESSEE 37401

400 Chestnut Street Tower II

USNRC REGION II
ATLANTA, GEORGIA

October 30, 1981 81 NOV 2 AIO 30

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Region II - Suite 3100
101 Marietta Street
Atlanta, Georgia 30303



Dear Mr. O'Reilly:

OFFICE OF INSPECTION AND ENFORCEMENT BULLETIN 80-20 -RII:JPO 50-518,
-519, -520, -521, -553, -554 - HARTSVILLE AND PHIPPS BEND NUCLEAR
PLANTS


TVA submitted its first, second, third, and fourth interim responses to the subject bulletin on September 12, 1980, February 10, June 15, and August 14, 1981, respectively. This letter constitutes the fifth interim response to the subject bulletin.

To date, none of the Westinghouse type W-2 switches have been identified at the Hartsville or Phipps Bend Nuclear Plants. GE is still awaiting information from other vendors and will transmit this information to TVA upon receipt. We anticipate transmitting the next report on or before January 29, 1982. If you have any questions, please call Jim Domer at FTS 858-2725.

To the best of my knowledge, I declare the statements contained herein are complete and true.

Very truly yours,

TENNESSEE VALLEY AUTHORITY


Mark R. Wisenburg
Nuclear Engineer

cc: Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
Division of Reactor Operations Inspection
Washington, DC 20555

8111170449 811030
PDR ADOCK 05000519
Q PDR