FORM NRC-591 (3-77)

U.S. NUCLEAR REGULATORY COMMISSION

OFFICE OF INSPECTION AND ENFORCEMENT

INSPECTION FINDINGS AND LICENSEE ACKNOWLEDGMENT

Re 12	actor Controls 45 S. Winchester Blvd. n Jose, California 9512	8	1450 Ma	tlear Regulatory Commission ria Lane, Suite 210 Creek, California 94596
3. 00	CKET NUMBER(S)	4. LICENSE NUMBER		Nov 6/198/
The in	nission's rules and regulations and the co-	nditions of your license. The	our license as the	ey relate to radiation safety and to compliance with the assisted of selective examinations of procedures and repress as a result of the inspection are as follows:
Sentar	No items of noncompliance or uns			gs as a result of their inspection are as follows.
The	following items of noncompliance re			e tound:
	A. Rooms or areas were not prope	rly posted to indicate th	he presence of	a PADIATION AREA. 10 CFR 20.203(b) or 34.42
	B. Rooms or areas were not properly posted to indicate the presence of a HIGH RADIATION AREA. 10 CFR 20.203(c) (1) or 34.42			
	C. Rooms or areas were not properly posted to indicate the presence of an AIRBORNE RADIOACTIVITY AREA. 10 CFR 20.203(d)			
	D. Rooms or areas were not properly posted to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(e)			
	E. Containers were not properly labeled to indicate the presence of RADIOACTIVE MATERIAL. 10 CFR 20.203(f) (1) or (f) (2)			
	F. A current copy of 10 CFR 20, a copy of the license, or a copy of the operating procedures was not properly posted or made available. 10 CFR 20.206(b)			
	G. Form NRC-3 was not properly posted, 10 CFR 20.206(c)			
	H. Records of the radiation exposure of individuals were not properly maintained. 10 CFR 20.401(a) or 34.33(b)			
	1. Records of surveys or disposals were not properly maintained. 10 CFR 20.401(b) or 34.43(d)			
	J. Records of receipt, transfer, disposal, export or inventory of licensed material were not properly maintained. 10 CFR 30.51, 40.61 or 70.51			
	K. Records of leak tests were not maintained as prescribed in your license, or 10 CFR 34.25(c)			
	L. Records of inventories were not maintained. 10 CFR 34.26			
	M. Utilization logs were not maintained. 10 CFR 34.27			
	N. Records of radiation survey instrument calibration were not maintained. 10 CFR 34.24			
	O Records of teletherapy electrical interlock tests were not maintained as prescribed in your license.			
	P. Other			
		Con	Mark	Grayson
	ne NRC Inspector has extined a nocompliance will be corrected wi			ompliance listed above. The items of
	8111190545 811106 NMS LIC30 04-15365-01 PE			IE01 51/0
	(Date)		(Licensee	Representative - Title or Position)