NOV 9 1981

License No. 53-16991-01MD

Pacific Radiopharmacy, Ltd. 347 North Kuakini Street Honolulu, Hawaii 96817

Attention: Phan The Tran, PhD

Director

Gentlemen:

Subject: NRC Inspection

This refers to the routine safety inspection conducted by Mr. J. F. Pang of this office on September 29, 1981 of activities authorized by NRC License No. 53-16991-01MD and to the discussion of our findings held by Mr. Pang with you and Mr. Rinaldi at the conclusion of the inspection.

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel and observations by the inspector.

During this inspection, it was found that certain of your activities appeared to be in noncompliance with NRC requirements. The items and references to the pertinent requirements are listed in Appendix A. These items have been categorized into severity levels as described in the Federal Register Notice (45 FR 66754) dated October 7, 1980.

The findings from this inspection, as well as the one conducted during October 20, 1980 indicate one repetitive item of noncompliance (see Appendix A, Item A(1).

8112030354 811109 NMS LIC30 53-16991-01 PDR

1E07

OFFICE .

PANG STAP 10/3 /81

THOMAS 11/6/81 BOOK 11/6/81

SPENCER / 11/6/81

A. JOHNSON 11/4/81

-2-NOV 9 1981 Pacific Radiopharmacy, Ltd. Pursuant to the action taken by the licensee relative to the violation stated in paragraph C. Appendix A. no further response to this item is required. We are concerned about the repetitive nature of the item of noncompliance observed during our inspection. In addition to the need for corrective action regarding the specific items of noncompliance included in Appendix A, we are concerned about the implementation of your management control system that allowed this repetitive item of noncompliance to recur. Consequently, in your reply you should describe in particular those actions taken or planned to improve the effectiveness of your overall management control system. Your response to this notice is to be submitted in accordance with the provisions of 10 CFR 2.201 as stated in Appendix A, Notice of Violation. We have adopted a new NRC enforcement policy, as described in the Federal Register Notice (45 FR 66754) dated October 7, 1980. With the adoption of that policy we are requiring, under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, that responses to Notices of Violations be submitted under oath or affirmation. Therefore, the last paragraph of your letter should include a statement equivalent to the following: "I certify that all information contained in this letter, including any supplements attached thereto, is true and correct to the best of my knowledge and belief." SIGNATURE DATE TITLE The signature should be notarized. If you have any questions on this matter or concerning this inspection, please telephone Mr. Pang on 415-943-3700.

-3- NOV 9 1981 pacific Radiopharmacy, Ltd. Our offices have moved recently. We call your attention to our new mailing address on the letterhead above. Sincerely, Original signed by H. E. Book George S. Spencer, Director Division of Technical Inspection Enclosures: Appendix A: Notice of Violation bcc: DMB/Document Control Desk (RIDS) Distributed by RV; State of Hawaii Engelken/Johnson LFMB