



Public Service Electric and Gas Company P.O. Box 168 Hancocks Bridge, New Jersey 08038

Salem Generating Station

June 17, 1981

Mr. Boyce H. Grier
Director of USNRC
Office of Inspection and Enforcement
1100
1100 Mark Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Grier:

REPORTABLE OCCURRENCE 81-35/01P
SALEM NO. 2 UNIT LER

This letter is to confirm our verbal report to the WRC Resident Inspector on Tuesday, June 16, 1981, advising of a potential reportable occurrence in accordance with Technical Specification 6.9.1.8.e.

During routine maintenance, check valves 21MS46 and 23MS46 were found to be damaged which resulted in these check valves being unable to perform their intended function. These valves are the No. 23 auxiliary feedwater turbine steam supply header isolation check valves.

An investigation is in progress and a detailed report will be submitted in the time period specified by the Technical Specifications.

Sincerely yours,

A handwritten signature in cursive script, appearing to read "H. J. Midura".

H. J. Midura
Manager - Salem Generating Station

JJE:dev

CC: General Manager - Nuclear Production
General Manager - Quality Assurance

8112040457 810831
PDR ADOCK 05000272
S PDR