
040Wm0 48910E

Wm-48



Department of Energy

Albuquerque Operations Office RETURN ORIGINAL TO PDR, HQ. P.O. Box 5400 Albuquerque, New Mexico 87115



Mr. Ramon E. Hall Jirector, Uranium Recovery Field Office Region IV U.S. Nuclear Regulatory Commission P.O. Box 25325 Denver, CO 80225



Dear Mr. Hall:

Attached is a report summarizing the dewatering investigations at the Durango, Colorado Uranium Mill Tailings Remedial Action Site. This report supplements the results and impacts of dewatering investigations that was presented during the February 22, 1990, meeting in Albuquerque, New Mexico.

Should you have any questions, please contact Elizabeth Damler of my staff at FTS 845-5654.

Sincerely, Thanks glarmes

Mark L. Matthews Acting Project Manager Uranium Mill Tailings Project Office

Attachment

cc w/o attachment: M. Abrams, UMTRA

9003150400 900222 M-48 WASTE PNU

DESIGNATED ORIGINAL Certified By Spange. Hord

ade 200- 0328