



Carolina Power & Light Company SERIAL: NLS-90-068

MAR 16 1990

United States Nuclear Regulatory Commission
ATTENTION: Document Control Desk
Washington, DC 20555

BRUNSWICK STEAM ELECTRIC PLAN, UNIT NO. 2
DOCKET NOS. 50-324/LICENSE NO. DPR-62
RECIRCULATION SYSTEM FLAW EVALUATION AND REPAIR REPORT

Gentlemen:

Attached is the "Design Report for Recirculation System Repair and Flaw Evaluation Performed During Fall, 1989 Refueling Outage at Brunswick Steam Plant Unit 2," prepared by Structural Integrity Associates. The evaluation results contained in this report were provided to the staff on March 7, 1990.

Please refer any questions regarding this matter to Mr. Dale B. Bates at (919) 546-6154.

Yours very truly,

M. R. Oates for LIL

L. I. Loflin
Manager
Nuclear Licensing Section

DBB/ecc (655ECC)

Attachment

cc: Mr. S. D. Ebnetter
Mr. N. B. Le
Mr. W. H. Ruland

9003220055 900316
PDR ADOCK 05000324
P FDC

*Aool
11*