

APPENDIX

U.S. NUCLEAR REGULATORY COMMISSION
REGION IV

NRC Inspection Report: 50-482/90-10

Operating License: NPF-42

Docket: 50-482

Licensee: Wolf Creek Nuclear Operating Corporation (WCNOC)

Facility Name: Wolf Creek Generating Station (WCGS)

Inspection At: WCGS, Burlington, Kansas

Inspection Conducted: March 12-16, 1990

Inspector:

Dale A. Powers for
A. B. Earnest, Physical Security Specialist
Security and Emergency Preparedness Section

4/2/90
Date

Approved:

Dale A. Powers
Dr. Dale A. Powers, Chief, Security and
Emergency Preparedness Section

4/2/90
Date

Inspection Summary

Inspection Conducted March 12-16, 1990 (Report 50-482/90-10)

Areas Inspected: Routine, unannounced inspection of the licensee's physical security program. The areas inspected within the physical security program included followup on previously identified inspection findings; management support, security program plan, and audits; protected area (PA) and vital area (VA) physical barriers; PA and VA access control of personnel, packages, and vehicles; alarm stations and communications; testing and maintenance; and land vehicle bomb contingency procedure verification.

Results: Within the program areas inspected, no violations or deviations were identified. The security program at WCGS appears to be well managed and receives the support of licensee management. The security force appears to be professional and motivated. The perimeter detection aids were recently upgraded and testing is ongoing to gain the optimum performance from the system. The licensee is currently completing an evaluation of the system and plans are well advanced to upgrade the camera system in the summer of 1990. Two open items requiring NRC followup are discussed in paragraph 3. These items detail problems with the security of keycard/badges and an incident wherein visitors were not properly escorted.

9005020065 900416
PDR ADOCK 05000482
Q PDC

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED

Further, an unresolved item is discussed in paragraph 3. This item details a physical security plan (PSP) change submitted under 10 CFR 50.54(p) that, in part, reduces the effectiveness of the PSP. This item will remain unresolved until the licensee reply to the issue is reviewed by NRC.

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION
UPON SEPARATION THIS
PAGE IS DECONTROLLED