

DCD/DCB

APR 17 1990

Diagnostic Services, Inc.  
ATTN: George C. Cassidy  
954 Circle Drive  
Green Bay, WI 54304

License No. 48-20341-01  
Docket No. 030-18274

Gentlemen:

This refers to the routine safety inspection conducted by Walter King of this office on March 21, 1990, of activities authorized by NRC Byproduct Material License No. 48-20341-01, and to the discussion of our findings with James Fett at the conclusion of the inspection.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. The inspection consisted of a selective examination of procedures and representative records, observations, independent measurements, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice. A written response is required.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC Public Document Room.

The responses directed by this letter and the accompanying Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

George M. McCann, Acting Chief  
Nuclear Materials Safety  
Section 1

Enclosure: Notice of Violation

RIII  
with  
4/12/90  
King/lms

RIII

McCann

9005070155 900417  
REG3 LIC30  
48-20341-01 PDC

1E07