

Region II

DML:MB:NB
(21674)

APR 26 1971

Puerto Rico Testing Services, Inc.
ATTN: Mr. Efrahim Murati
P. O. Box 2948
San Juan, Puerto Rico 00936

Gentlemen:

In order to continue review of your application dated April 7, 1971 which requests authorization to use the Technical Operations Model 414 source changer, we need a copy of your revised operating and emergency procedures which instructs radiographers in source exchange procedures. In addition, your procedures should be revised to include the inspection and maintenance program required by 10 CFR Part 34. A Notice dated November 20, 1970, was sent to you concerning this matter. The enclosed licensing guide provides information concerning such a program. The instructions to personnel should include steps to be taken in the event any deficiencies are found in equipment during the course of the inspections. A checklist for performance of the daily inspections should be developed which may also serve as a record of performance of the inspections.

We shall be pleased to continue review of your application upon receipt of the revised operating and emergency procedures in the form in which they will be given to radiographic personnel.

Sincerely,

ORIGINAL SIGNED BY
NATHAN BASSIN

Nathan Bassin
Materials Branch
Division of Materials Licensing

Enclosure:
AEC Licensing Guide--
Industrial Radiography

St. Br. Dist.
CO:II

CRESS
T-2 Ref-10

DML
NBassin:tt

4/23/71
9302250067 921007
PDR FOIA
APONTE92-328 PDR

APR 20 10 31 AM '71
VICTORY CV
CONFERENCE II
D 2 5 E C