

SOUTHERN CALIFORNIA EDISON <small>AN EDISON INTERNATIONAL COMPANY</small>		SONGS RADIOLOGICAL SURVEY		SOUTHERN CALIFORNIA EDISON <small>AN EDISON INTERNATIONAL COMPANY</small>		DATE <u>05 / 27 / 2014</u>		TIME <u>1020</u>		Page <u>1</u> of <u>1</u>	
UNIT	N	SURVEY REASON <input type="checkbox"/> Routine <input type="checkbox"/> Job Coverage <input type="checkbox"/> Pwr Entry _____ % <input checked="" type="checkbox"/> Other <u>Confirmatory Surveys</u>	<input type="checkbox"/> Post-Decon	<input type="checkbox"/> Pre-Job	SURVEY NO.	<u>140527-005</u>		<div style="text-align: center;"> BLDG. E-50 Rm. 22 Floor Monitor BKG. = 35 cps 2-1 BKG. = 60 cpm ASP1-SPA3 BKG. = 10000 cpm </div>			
AREA	YD		<input type="checkbox"/> Shipment/Receipt		MO NO.	N/A					
ELEV	N/A		<input type="checkbox"/> Source/Leak Test		REP NO.						
ROOM	E-50		<input checked="" type="checkbox"/> Other <u>Confirmatory Surveys</u>		EQUIP. ID.						

SMEARS						MASSLINNS		
NO.	β - γ	α	NO.	β - γ	α	NO.	Gross dpm	Hot Part. (Y/N)
1	<1K	N/A	16	<1K	N/A	A	N/A	N
2			17			B		
3			18			C		
4			19			D		
5			20	<1K		E		
6			21	N/A		F		
7			22					
8			23					
9			24					
10			25					
11								
12								
13								
14								
15	<1K	N/A		N/A	N/A		N/A	N

SURVEY CLASS
☐ Trend Pt. ☐ Component
☐ Boundary ☒ General Area ☐ Individual

SURVEY DESCRIPTION: Mesa Confirmatory Surveys

REMARKS: All accessible floor area scanned using the floor monitors. All Survey points consist of direct frisk readings and 100 cm2 smears. SPA3 readings over top of floor drains. No readings above BKG. detected during survey.

4 Floor Drains in the room.

Instruments used

Model	FLM3B	FLM3B	2-1	ASP1-SPA3
Serial No.	01	02	271981	1869

TECHNICIAN
 Print B. Dynes/M. Crumes/J. Papson
 Sign
APPROVED BY
 Print
 Sign
 Approval Date: 6/24/14 Time: 1430

SURVEY TYPE
☐ Shutdown (S/D)
Reference Number
 SO123-VII-20.9
Form Number
 SCE HP (2/3) 1259-1000
 REV. 3 09/07

Survey Points 1,3,4,6,8 and 10 are on the floor.

Survey Points 2,5,7 and 9 are on floor drains.

Survey Points 11-18 are on the interior walls.

Survey Point 19 is in the Fume Hood.

Survey Point 20 is on the scale.

Denotes Floor Drain.

Denotes Floor area surveyed.