

APPENDIX A

NOTICE OF VIOLATION

Radiation Monitoring Devices, Inc.  
Watertown, Massachusetts 02172

Docket Nos. 030-10806  
030-22008  
License Nos. 20-16325-01  
20-16325-02G

As a result of the inspection conducted on January 15, 1993, and in accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (Enforcement Policy) (1993), the following violation was identified:

10 CFR 71.5(a) requires that licensees who transport licensed material outside the confines of their plants or deliver licensed material to a carrier for transport comply with the applicable requirements of the regulations appropriate to the mode of transport of the Department of Transportation (DOT) in 49 CFR Part 170-189.

49 CFR 172.203(c)(2) requires, in part, that the letters "RQ" shall be entered on the shipping paper.

Contrary to the above, on February 20, 1992, the letters "RQ" were not entered on the shipping papers. Specifically, a Model 200, Compuglass device containing 360 millicuries of americium-241 was shipped to a general licensee without the required "RQ" on the shipping paper.

This is a Severity Level IV violation (Supplement V).

Pursuant to the provisions of 10 CFR 2.201, Radiation Monitoring Devices, Inc. is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including: (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

OFFICIAL RECORD COPY - S:\PENDING\RAD.MON - 02/16/93

RETURN ORIGINAL TO  
REGION I

IE-07

9303090442 930217  
PDR ADOCK 03010806  
C PDR