



Northern States Power Company

414 Nicollet Mall  
Minneapolis, Minnesota 55401-1927  
Telephone (612) 330-5500

March 2, 1993

Report Required by  
10 CFR Part 50, Section 50.73

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555


MONTICELLO NUCLEAR GENERATING PLANT  
Docket No. 50-263 License No. DPR-22

Main Steam Isolation Valves Local Leak  
Rate Exceeded - Root Cause to be Determined

The Licensee Event Report for this occurrence is attached. This report contains the following new NRC commitments:

1. Further evaluation of this event will be performed to confirm the root cause or causes. The results of this evaluation will be used to develop appropriate long term corrective actions to prevent recurrence.
2. The Main Steam Isolation Valves will be repaired and re-tested satisfactorily prior to startup.
3. A supplement to this report will be submitted prior to start-up to discuss the results of our root cause evaluation and to describe our long term corrective actions.

Please contact Terry Coss, Sr Licensing Engineer, at (612) 295-1449 if you require further information.

  
Thomas M Parker  
Director of Licensing  
Nuclear Generation

080083

c: Regional Administrator - III NRC  
Sr Resident Inspector, NRC  
NRR Project Manager, NRC  
State of Minnesota,  
Attn: Kris Sanda

Attachment

9303090469 930302  
PDR ADOCK 05000263  
S PDR

JE22