

NOTICE OF VIOLATION

Indiana State University
Terre Haute, IN

License No. 13-09639-05
Docket No. 030-00706

During an NRC inspection conducted on February 22 and 23, 1993, violations of NRC requirements were identified. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1992), the violations are listed below:

1. License Condition No. 19 requires that licensed material be possessed and used in accordance with the statements, representations, and procedures contained in certain referenced applications and letters.

The referenced letter dated April 29, 1988, states in Item 1.b. that an audit of the records and a review of the activities of the Radiation Safety Officer will be performed annually by the Radiological Control Committee.

Contrary to the above, in 1992, an audit of the records and a review of the activities of the Radiation Safety Officer were not performed by the Radiological Control Committee.

This is a repeat Severity Level IV violation (Supplement VI).

2. License Condition No. 19 requires that licensed material be possessed and used in accordance with the statements, representations, and procedures contained in certain referenced applications and letters.

The Radioisotope Handling Procedures contained in the referenced application dated November 1987 states in the section entitled "REGULATION PERTAINING TO RADIOISOTOPE LABORATORIES" that smoking, eating, or drinking is prohibited in the radioisotope laboratories. Drinking or eating utensils, such as coffee cups, are not to be located at any time in these laboratories.

Contrary to the above, on February 23, 1993, a bottle of champagne was located inside a refrigerator containing radioactive material in laboratory room number 280 of the Science Building.


This is a Severity Level IV violation (Supplement VI).

Pursuant to the provisions of 10 CFR 2.201, Indiana State University is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, Region III, 799 Roosevelt Road, Glen Ellyn, Illinois, 60137, within 30 days of the date of the letter transmitting this Notice of Violation (Notice). This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason

for the violation, or, if contested, the basis for disputing the violation; (2) the corrective steps that have been taken and the results achieved; (3) the corrective steps that will be taken to avoid further violations; and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order may be issued to show cause why the license should not be modified, suspended, or revoked, or why such other action as may be proper should not be taken. Where good cause is shown, consideration will be given to extending the response time.

MAR 16 1993

Dated _____



B. J. Holt, Chief
Nuclear Materials Inspection
Section 1