

SAFETY INSPECTION

Page 1 of 2

1. LICENSEE

University of Virginia
Rectors and Visitors
Office of Environmental Health and Safety

2. REGIONAL OFFICE

REGION II
U S NUCLEAR REGULATORY COMMISSION
101 MARIETTA STREET NW SUITE 2900
ATLANTA GA 30323

3. DOCKET NUMBER(S)

030-00510

4. LICENSE NUMBER(S)

45-00034-09

5. DATE OF INSPECTION

January 26, 1993

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The findings as a result of this inspection are as follows:

- ☐ 1. Within the scope of this inspection, no violations were observed.
- ☒ 2. The inspector also verified the steps you have taken to correct the violations identified during the last inspection. We have no further questions on those actions at this time.
- ☒ 3. During this inspection certain of your activities, as described below or attached, were in violation of NRC requirements. This form is a **NOTICE OF VIOLATION**, which is required to be posted in accordance with 10 CFR 19.11.
- ☐ A. _____ was not properly posted to indicate the presence of a _____ 10 CFR 20.203(b),(c),(d),(e) or 34.42.
- ☐ B. _____ of sealed sources were not performed at the proper frequencies. 10 CFR _____ or License Condition Number _____
- ☐ C. Records of _____ were not properly maintained. 10 CFR _____ or License Condition Number _____
- ☐ D. Documents were not properly posted or otherwise made available. 10 CFR 19.11.
- ☐ E. Reports or notification of _____ were not made in accordance with 10 CFR _____ or License Condition Number _____
- ☒ F. Timer linearly not evaluated over entire range of use on 6/17-18/1992, full calibration and during spot checks since 11/15/1991, as required by 10CFR 35.632(b)(4) and 35.634(a)(1).

9304300138 930129
PDR ADOCK 03000510
C PDR

1070

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

SIGNATURE -- LICENSEE

Ralph Allen

DATE

1/29/93

SIGNATURE -- NRC INSPECTOR

[Signature]

DATE

1/29/93

SAFETY INSPECTION

Page 2 of 2

1. LICENSEE

University of Virginia
Rectors and Visitors
Office of Environmental Health And Safety

2. REGIONAL OFFICE

REGION II
U S NUCLEAR REGULATORY COMMISSION
101 MARIETTA STREET NW SUITE 2900
ATLANTA GA 30323

3. DOCKET NUMBER(S)

030-00510

4. LICENSE NUMBER(S)

45-00034-09

5. DATE OF INSPECTION

January 26, 1993

3. (Continued)

☐ G.☐ H.☐ I.

☐ 4. The violations listed below are not being cited because ~~they were self-identified, and~~ corrective action was or is being taken, and the remaining criteria in 10 CFR 2, App. C, to exercise discretion were satisfied.

☐ A. Spot check records did not include determined accuracy of all measuring and localization devices, as required by 10 CFR 35.634(f).

☐ B. Documents were not properly posted or otherwise made available. 10 CFR 21.6

☐ C.