



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV
611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

MAY 5 1993

Docket: 030-20836
License: 25-21479-01

Mattingly Testing Services, Inc.
ATTN: Mark Mattingly, President
P.O. Box 3126
Great Falls, Montana 59403

Gentlemen:

SUBJECT: NRC INSPECTION REPORT 030-20836/93-01

This refers to the routine, unannounced inspection conducted by R. Brown of this office on April 28, 1993. The inspection included a review of activities authorized by Byproduct Material License 25-21479-01. At the conclusion of the inspection, the findings were discussed with members of your staff.

The inspection was an examination of activities conducted under the license as they relate to radiation safety and to compliance with the Commission's rules and regulations and the conditions of the license. The inspection consisted of selective examinations of procedures and representative records, interviews of personnel, independent measurements, and observation of activities in progress.

No violations or deviations were identified; therefore, no response to this letter is required.


This inspection did not include observations of work practices at temporary jobsites. The inspection revealed that although your radiography program involves only a few employees, sufficient management oversight and resources are devoted to the radiation safety program. It was also noted that you perform radiography in several Agreement States and that proper notification of officials was done prior to entering state jurisdiction.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter will be placed in the NRC Public Document Room.

Mattingly Testing Services, Inc. -2-

Should you have any questions concerning this letter, please contact the inspector identified above at (817) 860-8100.

Sincerely,

A handwritten signature in cursive script that reads "William L. Fisher".

William L. Fisher, Chief
Nuclear Materials Licensing Section

cc:
Montana Radiation Control Program Director

Mattingly Testing Services, Inc.

-3-

bcc:

DMB - Original (IE-07)

1/0

JLMilhoan

LJCallan

DDChamberlain

MRodriguez, OC/LFDCB (4503)

*WLFisher

*CLCain

*R. Brown

*NMIS

*MIS System

*RIV Files (2)

*REHall, URFO

*W/IFS Form

RIV:NMLS	C:NMLS			
RBrown:nh	WLFisher			
5/5/93	5/5/93			

100003

Mattingly Testing Services, Inc.

-3-

bcc:

DMB - Original (IE-07)

JLMilhoan

LJCallan

DDChamberlain

MRodriguez, OC/LFDCB (4503)

*WLFisher

*CLCain

*R. Brown

*NMIS

*MIS System

*RIV Files (2)

*REHall, URFO

*W/IFS Form

RIV:NMLS	C:NMLS			
RBrown:nh	WLFisher			
5/5/93	5/5/93			