



UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION I
631 PARK AVENUE
KING OF PRUSSIA, PENNSYLVANIA 19406

22 JUN 1981

Docket No. 50-309

Maine Yankee Atomic Power Company
ATTN: Mr. Robert H. Groce
Senior Engineer - Licensing
1671 Worcester Road
Framingham, Massachusetts 01701

Gentlemen:

Subject: Inspection 50-309/81-07

This refers to the special safeguards inspection conducted by Mr. W. Madden of this office on February 27 - March 3, 1981 at the Maine Yankee Atomic Power Station, Wiscasset, Maine of activities authorized by NRC License No. DPR-36 and to the discussions of our findings held by Mr. Madden with Mr. E. Wood and other members of your staff at the conclusion of the inspection.

Areas examined during this inspection are described in the Office of Inspection and Enforcement Inspection Report which is enclosed with this letter. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector.

Within the scope of this inspection, no items of noncompliance were observed.

In accordance with Section 2.790(d) of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, documentation of findings of your control and accounting procedures for safeguarding special nuclear materials and your facility security measures for physical protection are deemed to be commercial or financial information within the meaning of 10 CFR 9.5(a)(4) and shall be subject to disclosure only in accordance with the provisions of 10 CFR 9.12; therefore, the enclosed inspection report will not be placed in the Public Document Room and will receive limited distribution.

No reply to this letter is required; however, should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

James H. Joyner, Chief, Technical
Inspection Branch, Division of
Engineering and Technical Inspection

8107100211 810622
PDR ADOCK 05000309
Q PDR

Enclosure: Office of Inspection and Enforcement Inspection
Report Number 50-309/81-07 (Contains 2.790(d) Info)



IE02
S
1/1