

CONTROL

NUMBER

016913

LER

NUMBER

76-44

# LICENSEE EVENT REPORT

Big Rock Point Plant

CONTROL BLOCK: 01/16/91/13

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME				LICENSE NUMBER												LICENSE TYPE				EVENT TYPE				
01	M	I	B	R	P	L	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	3
7	8	9	14	15	25	26	30	31	32															

REPORT TYPE		REPORT SOURCE		DOCKET NUMBER				EVENT DATE				REPORT DATE													
01	CONT	L	L	0	5	0	-	0	1	5	5	1	2	2	0	7	1	6	0	1	2	0	7	1	7
7	8	57	58	59	60	61	68	69	74	75	80	76	77	78	79	84	85	86	87	88	89	90			

EVENT DESCRIPTION

02 The emergency diesel generator starting time exceeded the timing criteria by 3 seconds during a test start. The diesel was test started satisfactorily later the same date. Event is repetitive. (RO-4-76)

03

04

05

06

SYSTEM CODE		CAUSE CODE		COMPONENT CODE				PRIME COMPONENT SUPPLIER		COMPONENT MANUFACTURER			VIOLATION		
07	E	E	E	E	N	G	I	N	E	A	C	1	7	0	N
7	8	9	10	11	12	17	43	44	47	48					

CAUSE DESCRIPTION

08 Twice weekly starting continues. Governor lubrication and fuel transfer design continues under investigation by plant personnel and the diesel manufacturer, representative.

09

10

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION			
11	E	0	8	5	NA	B	NA	NA				
7	8	9	10	12	13	44	45	46				

  

FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY				LOCATION OF RELEASE			
12	Z	Z	NA								
7	8	9	10	11	44	45					

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION			
13	Z	NA			
7	8	9	11	12	13

PERSONNEL INJURIES

NUMBER	DESCRIPTION			
14	NA			
7	8	9	11	12

PROBABLE CONSEQUENCES

15 None

LOSS OR DAMAGE TO FACILITY

TYPE	DESCRIPTION		
16	NA		
7	8	9	10

PUBLICITY

17 None

ADDITIONAL FACTORS

18 None

19

