UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION

DOCKETED

BEFORE THE ATOMIC SAFETY AND LICENSING BOARD '81 NOV -5 P2:17

In the Matter of)	OFFICE OF SECRETARY DOCKETING & SERVICE
UNION ELECTRIC COMPANY	1	Docket No. STN 50-483-OL BRANCH
(Callaway Plant, Unit 1))	

ADDITIONAL EXHIBIT TO JOINT INTERVENORS' ANSWERS TO APPLICANT'S AND STAFF'S MOTIONS FOR SUMMARY DISPOSITION

Attached hereto is Exhibit 22 to Joint Intervenors' Answers to Applicant's and Staff's Motion for Summary Disposition. This Exhibit was omitted from the Exhibits filed October 30, 1981.

CHACKES AND HOARE


Kenneth M. Chackes #27534 Attorneys for Joint Intervenors

314 North Broadway

St. Louis, Missouri 63102 314/241-7961

STITION TO STATE OF THE STATE O

DS03



Ref: (a) BLSM-3284 dtd. 10/21/76: Bechte1/SMUPPS QA Program Review

Dear Mr. Stone:

In the course of the subject audit, several items of concern were identified in the Sechtel quality program, two of which are judged to warrant prompt follow-up actions by Sechtel management. Required management actions reviewed with Bechtel on October 28th are confirmed as follows:

Miscellaneous Steel Fabrication

Examination of Bechtel Surveillance Inspection Reports over the past few months indicates the nonconformances have been and are continuing to be identified involving fabricated steel produced by Cives Corp. Specifically, Sechtel in-spection activities which are based on a sampling level of 20-25 percent have identified nonconformances involving more than 300 pieces of misfabricated steel. These include discrepancies such as mislocated studs; weld undercut; oversize ended holes and painting defects. Discussion with the Decutel Inspection Supervisor indicates other nonconmances have been identified in addition to those listed in the Bechtel Inspection Reports. Additionally, nonconforming material has recently been detected at Callaway Site (see: NCR No. 2-0017-C-A dtd. 10/12/75) raising further questions with respect to the suppliers performance. Unile data exists indicating actions are being taken to resolve each discrepancy on a case basis, follow-up ranagement actions are required by Sucriel to examine and, if appropriate, upgrade supplier performance. Follow-up actions to resolve supplier

Exhibit 22

5-67 - 100° Statement

performance deficiencies of the type indicated is necessary to accomplish the Bechtel commitments of Ref. (a).

Bechtel Management is requested to re-examine the overall performance of this supplier and, recommend a course of action in view of the number of nonconformances being generated. An initial draft of the Bechtel plan is to be available for SNUPPS review by November 15, 1976.

Vendor Quality Program

Review of the Anchor-Darling QA Manual approved by Sechtel for use on the design and fabrication of nuclear valves for SNUPPS indicates that this supplier's manual is limited to pressure boundary components and parts covered by ASME-Boiler and Pressure Vessel Code and has not been extended to other safety-related, non-Code items or parts as required. It is SNUPPS understanding that ASME-acceptable manuals have been approved for use by other valve and equipment suppliers without similarly having been extended or otherwise supplemented to cover safety-related non-Code items or parts. As discussed with Bechtel on October 28th, it is understood that prompt actions are being taken to assure that ongoing supplier activities involving safety-related components or parts are performed in accordance with approved quality programs. Bechtel is requested to advise SHUPPS of the results of those actions by Navember 15, 1976.

The above items and required follow-up actions will be included in the audit report to be transmitted to Becntel together with other audit findings. Pending completion and transmittal of the final report, Bechtel is requested to proceed with corrective actions as indicated above.

Very truly yours,

S. J. Seike QA Manager

SJS/jh

cc: J. M. Amaral

T. I. Gillespie

J. L. Turdera

C. E. Bald

UNITED STATES OF AMERICA NUCLEAR REGULATORY COMMISSION

BEFORE THE ATOMIC SAFETY AND LICENSING BOARD

In the Matter of)			
UNION ELECTRIC COMPANY	.)	Docket	No. STN	50-483-OL
(Callaway Plant, Unit 1)	,			

CERTIFICATE OF SERVICE

I hereby certify that copies of Additional Exhibit to Joint Intervenors' Answer to Applicant's and Staff's Motions for Summary Disposition have been served on the following by deposit in the United States mail this 2nd day of November, 1981.

James P. Gleason, Esq., Chairman Atomic Safety and Licensing Board 513 Gilmoure Drive Silver Spring, MD 20901

Mr. Glenn O. Bright Atomic Safety and Licensing Board Panel U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Dr. Jerry R. Kline Atomic Safety and Licensing Board Panel U.S. Nuclear Regulatory Commission Washington, D.C. 2055

Thomas A. Baxter, Esq. Shaw, Pittman, Potts & Trowbridge 1800 M Street, N.W. Washington, D.C. 20026

Docketing and Service Section Office of the Secretary U.S. Nuclear Regulatory Commission Washington, D.C. 20555

Roy P. Lessy, Jr., Esq. Office of the Executive Legal Director U.S. Nuclear Regulatory Commission Washington, D.C. 20555

> Kenneth M. Chackes CHACKES AND HOARE