

Bechtel Power Corporation

Engineers - Constructors

12400 East Imperial Highway

Norwalk, California 90650

MAIL ADDRESS

P.O. BOX 60860 - TERMINAL ANNEX, LOS ANGELES, CALIFORNIA 90060

TELEPHONE (213) 864-6011



December 3, 1981

Mr. Karl Seyfrit
Director, Region IV
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012



Subject: Improper Sized Wire Connectors on Radiation Monitoring Devices

Reference: Southern California Edison 10 CFR 50.55(e) Report dated
October 23, 1981. Docket Nos. 50-361 and 50-362, San Onofre
Nuclear Generating Station, Units 2 & 3

Dear Mr. Seyfrit:

On October 23, 1981, Southern California Edison, San Onofre Units 2 and 3, informed Mr. Engelken, U.S. Nuclear Regulatory Commission Region V, of the subject deficiency.

Subsequent evaluation by the Bechtel Review Committee concludes that the condition is also reportable under 10 CFR Part 21. The Southern California Edison report contains all the information required by Part 21 with the exception of the information required by 21.21(b)(3) VI as it is unknown to Bechtel.

Nuclear Measurements Corporation will be advised by letter that the component as applied by Bechtel contains a substantial safety hazard defect and will be requested to review its responsibility for compliance to Part 21, Section 21.21(b)(3) VI.

Other Bechtel Divisions were advised of the defect by appropriate records and correspondence.

Sincerely,

BECHTEL POWER CORPORATION

A handwritten signature in dark ink, appearing to read "R. L. Patterson".

R. L. Patterson

Manager of Division Quality Assurance

RLP:JHS:db

8112110228 811203
PDR ADOCK 05000361
S PDR

IE 27
S/10