LICENSEE EVENT REPORT

LICENSEE EVENT REPORT
CONTROL BLOCK: [] [] (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 N Y J A F 1 2 0 0 - 0 0 0 - 0 0 3 4 1 1 1 1 4 5 5 LICENSE CODE 14 15 LICENSE NUMBER 26 LICENSE TYPE 30 57 CAT 58
REPORT L 6 0 5 0 0 0 0 3 3 3 7 0 6 0 4 8 1 8 1 2 1 7 8 1 3 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10 During normal operation, drywell equipment drain sump pump 'B' lost suction and
[0]3] [could not effect sump pump out. Pump 'A' and the components of the leakage 1
[0] 4] [monitoring system, which provides sump level, pump out flow rate and flow
[0] 5] [integration used to meet TS 4.6.D, were fully operable. TS 3.6.D.2 was not clear
[0] [with respect to pump operability requirements however, the ability to monitor and
olf determine leakage was not impaired. No significant hazard existed.
0 8 0
SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
(17) REPORT 8 1 22 23 24 26 27 28 29 30 31 32 32 32 32 33 34 34 35 37 36 37 37 38 39 30 31 32 32 30 31 32 32 32 33 34 35 36 37 37 37 38 38 38 38 38
[1] [ing and lubrication of the valve. The plant requested and received TS Amendment
[1] Which provides clarification that individual pump operability is not the subject
[1] Of a Limiting Condition for Operation. LER 81-021 is a related event.
FACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32
7 3 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 1 6 Z 33 Z 34 NA 44 45 46 LOCATION OF RELEASE 36
7 8 9 10 11 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39 1 7 0 0 0 0 37 Z 38 NA
7 8 9 11 12 13 80 PERSONNEL INJURIES
NUMBER O SECRIPTION NA NA
LOSS OF OR DAMAGE TO FACILITY (43) TYPE DESCRIPTION NA
PUBLICITY SSUED DESCRIPTION 45 STANDOCK OSO00333 PDR P
NAME OF PREPARER W. Verne Childs PHONE 315-342-3840