



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P O BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

December 16, 1981

G. D. McLendon
Senior Vice President

W3K-81-0453
Q-3-A35.07

Mr. J. T. Collins, Director, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

Subject: Waterford SES Unit 3
Docket No. 50-382
Final Report of Potentially
Significant Construction Deficiency No. 54
"Repetitive Failures of Limitorque Operator"



Reference: LP&L Letter, W3K 81-0397 to USNRC dated October 30, 1981

Dear Mr. Collins:

We have completed our evaluation of the reportability of the subject deficiency under 10CFR50.55(e) and have determined that it is not reportable. The results of our review are on file at the Waterford SES Unit 3 site and are available for your inspection.

Very truly yours,

G. D. McLendon

GDMcL:RGP:grf

- cc: 1) Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8112290126 811216
PDR ADOCK 05000382
S PDR

IE 27
3/10