

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0	1	1	L	Q	A	D	1	2	0	0	0	-	0	0	0	3	4	1	1	1	1	4	5			
7	8	9	LICENSEE CODE					14	15	LICENSE NUMBER							25	26	LICENSE TYPE				30	57	CAT	58

0	1	L	6	0	5	0	0	0	2	5	4	7	1	1	2	1	3	1	8	1	9	1	2	1	4	8	1	9
7	8	REPORT SOURCE		80	81	DOCKET NUMBER						68	69	EVENT DATE				74	75	REPORT DATE				80				

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | On November 21, 1981, Unit One was shutdown for a scheduled maintenance outage.

0 3 | Using the "A" RHR Service Water Loop to supply cooling water for shutdown cooling,

0 4 | water was found entering the Turbine elevator shaft at approximately 32 feet from

0 5 | the bottom of the shaft. The probable consequences are minimal as cooling water

0 6 | supply as changed to the "B" loop. The water leakage was river water and therefore,

0 7 | presents no radiological problems.

0 8 | \_\_\_\_\_

0	9	C	F	11	B	12	C	13	P	I	P	E	X	X	14	E	15	Z	16																						
7	8	SYSTEM CODE		9	10	CAUSE CODE		11	CAUSE SUBCODE		12	COMPONENT CODE				13	COMP SUBCODE		19	VALVE SUBCODE		20																			
17	LER/RO REPORT NUMBER		8	1	EVENT YEAR		21	22	SEQUENTIAL REPORT NO.		0	2	0	OCCURRENCE CODE		28	29	REPORT TYPE		L	30	REVISION NO.		0	32																
ACTION TAKEN		F	18	FUTURE ACTION		F	19	EFFECT ON PLANT		Z	20	SHUTDOWN METHOD		Z	21	HOURS		0	0	0	0	22	ATTACHMENT SUBMITTED		N	23	NPRD-4 FORM SUB.		Y	24	PRIME COMP. SUPPLIER		Z	25	COMPONENT MANUFACTURER		G	2	5	5	26
33	34	35	36	37	40	41	42	43	44	47																															

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | The cause of the occurrence is not known at this time. The underground section of

1 1 | the piping was isolated with cooling water being supplied to the Unit One "A" loop

1 2 | from a Unit One to Unit Two cross-tie. A supplemental report will be issued

1 3 | following determination of the cause and final corrective action.

1 4 | \_\_\_\_\_

1	5	G	28	0	0	0	29	NA	30	A	31	Operator	32	Observation			
7	8	FACILITY STATUS		9	10	% POWER		12	13	METHOD OF DISCOVERY		45	46	DISCOVERY DESCRIPTION		80	
1	6	Z	33	Z	34	ACTIVITY CONTENT RELEASED OF RELEASE		35	NA	AMOUNT OF ACTIVITY		44	45	LOCATION OF RELEASE		36	80
1	7	0	0	0	37	Z	38	PERSONNEL EXPOSURES		39	NA						
7	8	PERSONNEL EXPOSURES NUMBER		9	11	PERSONNEL INJURIES		40	NA	DESCRIPTION		41					
1	8	0	0	0	40	LOSS OF OR DAMAGE TO FACILITY		43	NA	DESCRIPTION		42					
7	8	PERSONNEL EXPOSURES NUMBER		9	11	LOSS OF OR DAMAGE TO FACILITY		43	NA	DESCRIPTION		42					
1	9	Z	42	PUBLICITY ISSUED		44	NA	DESCRIPTION		45							
7	8	PUBLICITY ISSUED		9	10	PUBLICITY DESCRIPTION		45									

GPO 91-7-929