

December 16, 1981

Log No. K81-306 File: RR 2 (NP-33-81-89)

Docket No. 50-346 License No. NPF-3

Mr. James G. Keppler Regional Director, Region III Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

Dear Mr. Keppler:

Reportable Occurrence 81-074 Davis-Besse Nuclear Power Station Unit 1 Date of Occurrence: November 16, 1981

Enclosed are three copies of Licensee Event Report 81-074 with a supplemental information sheet which are being submitted in accordance with Technical Specification 6.9 to provide 30 day written notification of the subject occurrence.

Yours truly,

Terry Oming

Terry D. Murray Station Superintendent Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Victor Stello, Jr., Director Office of Inspection and Enforcement Encl: 30 copies

> Mr. Norman Haller, Director Office of Management and Program Analysis Encl: 3 copies

Mr. Luis Reyes NRC Resident Inspector Encl: 1 copy

8112290399 8112 PDR ADDCK 05000



DEC 2 1 1981

300 MADISON AVENUE TOLEDO, OHIO 43652

THE TOLEDO EDISON COMPANY EDISON PLAZA