



LER NO. 50-368/81-044/03L-0

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (continued)

the DNBR calculations was changed in all CPC channels to incorporate the appropriate rod bow penalty. COLSS was also updated to reflect the increased rod bow penalty. The surveillance procedure used to monitor core power distribution has been modified to incorporate the monitoring of rod bow penalty acceptability. Completion of NRC review of the C-E rod bow penalty topical report should allow deletion of the additional penalties presently required by T.S.4.2.4.4.