TENNESSEE VALLEY AUTHORITY CHATTANOOGA, TENNESSEE 37401

1750 Chestnut Street Tower IA 9 . 54

December 23, 1981

Mr. James P. O'Reilly, Director U.S. Nuclear Regulatory Commission Office of Inspection and Enforcement Region II 101 Marietta Street, Suite 3100 Atlanta, Georgia 30303

Dear Mr. O'Reilly:

TENNESSEE VALLEY AUTHORITY - BROWNS FERRY NUCLEAR PLANT UNIT 1 - DOCKET NO. 50-259 - FACILITY OPERATING LICENSE DPR-33 - REPORTABLE OCCURRENCE REPORT BFRO-50-259/81081

The enclosed report provides details concerning 1 EN reactor motor-operated valve board motor-generator set which was removed from service due to loss of lubrication on generator coupling. This report is submitted in accordance with Browns Ferry unit 1 Technical Specification 6.7.2.b(2).

Very truly yours,

TENNESSEE VALLEY AUTHORITY

Director of Nuclear Power

Enclosure (3) cc (Enclosure): Director (3) Office of Management Information and Program Control U.S. Nuclear Regulatory Commission Washington, DC 20555

Director (40) Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, DC 20555

Records Center Institute of Nuclear Power Operations 1820 Water Place Atlanta, Georgia 30339

Mr. R. F. Sullivan, NRC Inspector, Browns Fer.

8112310120 811 PDR ADOCK 0500

An Equal Opportunity Employer