


Washington Public Power Supply System

Box 1223 Elma, Washington 98541 (206) 482-4428

Docket Numbers 50-508 and 50-509

December 28, 1981
G03-81-2870



Document Control Desk
U. S. Nuclear Regulatory Commission
Washington D. C. 20555

Subject: PROJECT NOS. 3 AND 5
DOCKET NUMBERS 50-508 AND 50-509
INTERIM REPORT OF POTENTIAL 10CFR50.55(e)
WELDING DEFICIENCIES, STEEL DOOR FRAME FABRICATION (D/N #039)

Attached is a copy of the interim report provided to Region V concerning a potential 10CFR50.55(e) associated with steel door frame welding deficiencies.

Should you have any questions or desire further information, please contact me directly.

R. S. Leddick (1000)
Program Director, WNP-3/5

DRC/tt

Attachment

cc: J. Adams - NESCO-WO/A
D. Smithpeter - BPA-WO/A
Ebasco - New York-WO/A
WNP-3/5 Files - Richland-WO/A

IE27
S/11

8112310402 811228
PDR ADOCK 05000508
S PDR