

Alabama Power Company
60C North 18th Street
Post Office Box 2641
Birmingham, Alabama 35291
Telephone 205 250-1000

RRPI

USNRC REGION II
ATLANTA, GEORGIA



Alabama Power
the southern electric system

81 DEC 28 9:50

December 18, 1981

F. L. CLAYTON, JR.
Senior Vice President

Docket No. 50-364/G

Mr. J. P. O'Reilly, Director
U. S. Nuclear Regulatory Commission
101 Marietta Street, N.W.
Suite 3100
Atlanta, GA 30303



Dear Mr. O'Reilly:

The following Special Report is being submitted in accordance with Unit 2 Technical Specification 3.7.12:

At 0830 on November 16, 1981 it was determined that the seal on fire barrier cable penetration 39-100-06, which is required to be operational by Technical Specification 3.7.12, had been damaged and was therefore declared inoperable. Alabama Power Company complied with Technical Specification 3.7.12 action statement requirements. Subsequent to completion of the necessary repairs, fire barrier cable penetration 39-100-06 was returned to service at 1600 on November 24, 1981. Training in the necessary administrative requirements will be given to those personnel responsible for implementing design changes involving the breach of a fire barrier.

Yours very truly,

F. L. Clayton, Jr.
F. L. Clayton, Jr.

FLCJr/RWS:cdb

xc: Mr. W. H. Bradford

8112310508 811218
PDR ADOCK 05000364
S PDR

0574-40-0075

Tezz
s/o