

POWER AUTHORITY OF THE STATE OF NEW YORK
INDIAN POINT NO. 3 NUCLEAR POWER PLANT

P. O. BOX 215 BUCHANAN, N. Y. 10511

TELEPHONE: 914-739-8200



December 22, 1981
IP-FWG-15846


Docket No. 50-286
License No. DPR-64

Ronald C. Haynes, Director
Office of Inspection and Enforcement
Region 1
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania 19406

Dear Mr. Haynes:

The attached Licensee Event Report LER 81-010/01T-0 is hereby submitted in accordance with the requirements of I. E. Bulletin 80-24, Prevention of Damage due to Water Leakage Inside Containment, Section 2.f. Three copies of this letter and attachment are enclosed as required. This constitutes the fourteen day report required by I. E. Bulletin 80-24 and supplements the twenty-four hour formal notification of December 9, 1981.

Very truly yours,


John C. Brons
Resident Manager

FWG/bam

cc: Director of Nuclear Reactor Regulation
Attn: William McDonald, Director (3 copies)
Office of Management Information & Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Office of Inspection and Enforcement (30 copies)
c/o Distribution Services Branch, DDC, ADP
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Mr. George Perry
Power Authority of the State of New York
10 Columbus Circle
New York, New York 10019

Resident Inspector T. Kenny
George Wilverding, NYC
J. P. Bayne, NYO
James Davis (SRC), NYO

Institute of Nuclear Power Operations
1820 Water Place
Atlanta, Georgia 30339

8201030315 811222
PDR ADOCK 05000286
S PDR



IE 22
5
1/1