

LICENSEE EVENT REPORT

CONTROL BLOCK: \_\_\_\_\_ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 M D C C N 2 2 0 0 - 0 0 0 0 0 - 0 0 3 4 1 1 1 1 4 5  
7 8 9 LICENSE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T  
0 1 REPORT SOURCE L 6 0 5 0 0 0 3 1 8 7 1 2 0 4 8 1 8 1 2 3 1 8 1 9  
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal power operation at 1230 with No. 22 charging pump out of  
0 3 service, No. 21 charging pump developed a packing leak and was isolated  
0 4 (T.S. 3.1.2.4). No. 21 charging pump was restored to service at 1550.  
0 5 No. 23 charging pump remained operable during this event. This is not  
0 6 a repetitive event.  
0 7  
0 8

0 9 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE  
P C 11 E 12 B 13 P U M P X X 14 E 15 Z 16  
7 8 9 10 11 12 13 18 19 20

17 LER/RO REPORT NUMBER 8 1 21 22  
SEQUENTIAL REPORT NO. 0 5 5 24 26  
OCCURRENCE CODE 0 3 28 29  
REPORT TYPE L 30 31  
REVISION NO. 0 32

ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED NPRD-4 FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER  
A 18 Z 19 Z 20 Z 21 0 0 0 0 22 N 23 Y 24 L 25 X 9 9 9 26  
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Cause of packing leak was flaking of ceramic coating on a charging pump  
1 1 plunger. This appears to be an isolated occurrence caused by a manufac-  
1 2 turing defect. Faulty plunger was replaced and the pump was repacked.  
1 3 Although further corrective action is unnecessary for this specific  
1 4 event, investigation of new packing and methods is ongoing.

1 5 FACILITY STATUS % POWER OTHER STATUS METHOD OF DISCOVERY DISCOVERY DESCRIPTION  
E 28 0 9 1 29 NA A 31 Operator Observation  
7 8 9 10 11 13 44 45 46 80

1 6 ACTIVITY RELEASED OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE  
Z 33 Z 34 NA NA  
7 8 9 10 11 44 45 80

1 7 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION  
0 0 0 37 Z 38 NA  
7 8 9 10 11 12 13 80

1 8 PERSONNEL INJURIES NUMBER DESCRIPTION  
0 0 0 40 NA  
7 8 9 10 11 12 80

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION  
Z 42 NA  
7 8 9 10 80

2 0 PUBLICITY ISSUED DESCRIPTION  
N 44 NA  
7 8 9 10 80

NAME OF PREPARER R.L. Wenderlich/D.E. Huseby PHONE: (301) 269-4776/4816

8201070117 811231  
PDR ADOCK 05000318  
S PDR

NRC USE ONLY