

TERA
10:40
40-2418

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF INSPECTION AND ENFORCEMENT

Region I

Report No. 81-01
Docket No. 40-2418
License No. SMB-96 Priority _____ Category _____
Licensee: National Beryllia Corporation
First and Haskill Avenue
Haskill, New Jersey 07420

Facility Name: _____

Inspection at:

Inspection conducted: ✓

Inspectors: [Signature]
C. Rowe, Radiation Specialist

12/11/81
date signed

Approved by: [Signature]
John D. Kinneman, Chief
Materials Radiological
Protection Section

12/15/81
date signed

Inspection Summary:

Telephone inquiry conducted October 22, 1981

Areas Covered: Expiration of license, disposal of licensed material.

Results: The Region I office has determined that this license should be retired.

DETAILS

1. Person Contacted

Mr. William J. Coch

2. Expiration of License

The inspector contacted the licensee by phone on October 22, 1981 and notified him that his License No. SMB-96 had expired on January 13, 1978. The licensee informed the inspector that he possessed no byproduct material and wished to have his license terminated. This was confirmed in a letter sent by the licensee to the Regional Office on November 17, 1981.

3. Evaluation by the Regional Office

Region I has evaluated the information supplied by the licensee and has determined that a closeout survey is not necessary and that this license should be retired.