

50-382



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345

December 3, 1981

D. L. ASWELL
Vice President-Power Production

W3K-81-0434
Q-3-A35.07.23

Mr. K. V. Seyfrit, Director, Region IV
U. S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76013

Subject: Waterford SES Unit 3
Significant Construction Deficiency No. 23
"Defective Valve Actuators (Fisher Controls)"
Fourth Interim Report



Reference: Telecon to L. Martin (NRC) from L. L. Bass (LP&L) dated 12/10/81

Dear Mr. Seyfrit:

The final report on the subject item was due to be submitted by November 30, 1981. At this time replacement material has been received and work orders have been issued to accomplish the replacement of the ten (10) valve actuators. It is estimated that this work will be completed by December 24, 1981.

Based on the above, a final report on Significant Construction Deficiency No. 23 will be submitted by January 8, 1982.

Yours very truly,

D. L. Aswell

DLA/LLB/grf

- cc: 1) Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

8201180475 811203
PDR ADOCK 05000382
S PDR

1827
Silo