



LOUISIANA
POWER & LIGHT

142 DELARONDE STREET
P. O. BOX 6008 • NEW ORLEANS, LOUISIANA 70174 • (504) 366-2345



January 5, 1982

G. D. McLENDON
Senior Vice President

W3K81-0481
Q-3-A35.07.17

Mr. John T. Collins, Regional Administrator, Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, Texas 76012

SUBJECT: Waterford SES Unit No. 3
Docket No. 50-382
Fourth Interim Report Significant Construction Deficiency No. 17
"Base Metal Defect in Main Steam and Feedwater Containment Penetration
Anchors"

REFERENCE: Interim Report W3K81-0386 dated 10/20/81

Dear Mr. Collins:

In the referenced interim report, LP&L committed to submit a final report on
Significant Construction Deficiency No. 17 by January 29, 1982.

Again the extent of repairs necessary to complete the corrective action on this
deficiency has made it impossible to meet this deadline.

A final report on this item will be submitted by March 17, 1982.

If there are any questions, please let us know.

Very truly yours,

G. D. McLendon

GDMcL:WMM:ncd

- 1) Director
Office of Inspection & Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555
- 2) Director
Office of Management
Information and Program Control
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

44-27
S/O

8201180523 820105
PDR ADOCK 05000382
S PDR