



January 7, 1982

Log No. K82-037
File: RR 2 (NP-33-81-78)

Docket No. 50-346
License No. NPF-3

Mr. James G. Keppler
Regional Director, Region III
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137



Dear Mr. Keppler:

Enclosed are three copies of NRC Form 366, Licensee Event Report 81-069 which has been revised to indicate the correct NPRD code in block 24. The change is indicated as Revision 1 to this form. There has been no change to the supplemental information sheet of this report.

Please replace your previous copies of this LER form with the attached corrected copies.

Yours truly,

Terry D. Murray /smq

Terry D. Murray
Station Superintendent
Davis-Besse Nuclear Power Station

TDM/ljk

Enclosure

cc: Mr. Victor Stello, Jr., Director
Office of Inspection and Enforcement
Encl: 30 copies

Mr. Norman Haller, Director
Office of Management and Program Analysis
Encl: 3 copies

Mr. Luis Reyes
NRC Resident Inspector
Encl: 1 copy

8201200308 620107
PDR ADOCK 09000346
S PDR

THE TOLEDO EDISON COMPANY EDISON PLAZA 300 MADISON AVENUE TOLEDO, OHIO 43652

IE 22
11

JAN 14 1982