



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE • POCHETER, N.Y. 14649

JOHN E. MAIER
VICE PRESIDENT

TELEPHONE
AREA CODE 716 546-2700

January 4, 1982



Mr. Ronald C. Haynes,
U.S. Nuclear Regulatory Commission
Office of Inspection and Enforcement
Region I
631 Park Avenue
King of Prussia, PA 19406

Subject: LER 81-022/01T-0, Error Discovered in the Transient or
Accident Analyses.
R.E. Ginna Nuclear Power Plant, Unit No. 1
Docket No. 50-244

Dear Mr. Haynes:

In accordance with Technical Specifications, article 6.9.2.a.8, "Errors discovered in the transient or accident analyses or in the methods used for such analyses as described in the safety analysis report or in the bases for the technical specifications that have or could have permitted reactor operation in a manner less conservative than assumed in the analyses", the attached licensee event report LER 81-022/01T-0 is hereby submitted.

Very Truly Yours,

John E. Maier

Attachment

CC: Document Control Desk (1)

8201250216 820104
PDR ADOCK 05000244
S PDR

IE22
51/1