

PILGRIM NUCLEAR POWER STATION
RFD #1 ROCKY HILL ROAD
PLYMOUTH, MASSACHUSETTS 02360

R. D. MACHON
NUCLEAR OPERATIONS MANAGER
PILGRIM STATION

January 13, 1982

BECo Ltr. #82-4



Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Licensee Event Report 81-054/01T-4 (UPDATE REPORT)

Docket Number 50-293
License DPR-35

Gentlemen:

The attached Licensee Event Report 81-054/01T-4 "Masonry Wall Design" is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.1.i.

For future block walls identified during Refuel V as being unstable, notification and available information will be verbally transmitted immediately to the on-site NRC Inspector. If the on-site Inspector is not available, the Region I Section Chief for Pilgrim Nuclear Power Station will be notified.

An update to LER 81-054/01T will be issued within fourteen (14) days of above verbal notification. This fourteen (14) day report will include a complete report on the most recently identified unstable block wall, information previously issued on other unstable block walls and a progress report of construction efforts to repair these walls.

If there are any questions on this subject, please contact us.

Respectfully submitted,

R. D. Machon
Nuclear Operations Manager
Pilgrim Station

MTM:ep

Enclosure: LER 81-054/01T-4

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8201260111 820113
PDR ADOCK 05000293
S PDR

JE22
3/11