



THE CLEVELAND ELECTRIC ILLUMINATING COMPANY

P.O. BOX 5000 ■ CLEVELAND, OHIO 44101 ■ TELEPHONE (216) 622-9800 ■ ILLUMINATING BLDG. ■ 55 PUBLIC SQUARE

Serving The Best Location in the Nation

Dalwyn R. Davidson
VICE PRESIDENT
SYSTEM ENGINEERING AND CONSTRUCTION

January 15, 1982



Mr. James G. Keppler
Director, Region III
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

RE: Perry Nuclear Power Plant Docket Nos.
50-~~440~~, 50-441; Significant Deficiency on
Sensitized Stainless Steel Pipe Spools
(RDC 38(81))

Dear Mr. Keppler:

Our last letter concerning this subject dated October 22, 1981, states that our final report is scheduled to be submitted to your office by January 15, 1982. In that letter it was stated that an extensive investigation is underway associated with the lack of solution heat treating after hot bending of pipe spools for Unit I Fuel Pool Cooling System. Due to the extent of this investigation, it has become necessary to request an extension of the date for submitting our final report to your office.

This was discussed with Mr. J. Streeter of your office on January 13, 1982, and he indicated that this would be acceptable. We now anticipate that the final report will be submitted by May 4, 1982.

Very truly yours,

Dalwyn R. Davidson, Vice President
System Engineering and Construction

cc: USNRC - Site

Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

U. S. Nuclear Regulatory Commission
c/o Document Management Branch
Washington, D.C. 20555

8201260236 820115
PDR ADOCK 05000440
PDR

JAN 20 1982

IE 27 1/6