ORGANIZATION:

WESTINGHOUSE ELECTRIC CORPORATION, INSTRUMENTATION DEPARTMENT

HUNT VALLEY, MARYLAND

REPORT NO.: 99900217/81-02 INSPECTION DATE(S): 11/16-19/81 INSPECTION ON-SITE HOURS:

CORRESPONDENCE ADDRESS: Westinghouse Electric Corporation

Instrumentation Department

ATTN: Mr. J. F. Heins, General Manager

1111 Schilling Road Hunt Valley, MD

ORGANIZATION CONTACT:

Mr. R. W. Lee, Product Assurance Manager

TELEPHONE: (301) 667-5532

PRINCIPAL PRODUCT: Electronic components and controls.

NUCLEAR INDUSTRY ACTIVITY: About 75% of manufacturing is commercial nuclear work. Solid State Protection Systems, Nuclear Instrumentation Systems, Digital Rod Position Indication Systems, Reactor and Containment Vessel Level Monitoring Systems, and Technical Support Centers are some of the product lines.

ASSIGNED INSPECTOR:

Components Section (CS)

OTHER INSPECTOR(S):

APPROVED BY: Potapovs, Acting Chief,

INSPECTION BASES AND SCOPE:

A. BASES: 10 CFR Part 50, Appendix B.

SCOPE: Nonconformances and corrective action; calibration; procurement controls; and status of previous inspection findings.

8201260419 820106 PDR QA999 EMVWEST

ORGANIZATION: WESTINGHOUSE ELECTRIC CORPORATION, INSTRUMENTATION DEPARTMENT

HUNT VALLEY, MARYLAND

REPORT NO.: 99900217/81-02 INSPECTION RESULTS: PAGE 2 of 3

A. VIOLATIONS:

None

B. NONCONFORMANCES:

- Contrary to the QA Manual, Section 14.1 and Criterion V of Appendix B to 10 CFR Part 50, two Inspection Control Tags were found with incorrect and missing information.
- Contrary to the QA Manual, Section 7.1, and Criterion V of Appendix B to 10 CFR Part 50, two Corrective Action Requests (CARs) for vendor nonconformances were either not initiated or were voided.
- Contrary to the QA Manual, Section 8.2 and Criterion V of Appendix B to 10 CFR Part 50, three cases were found where defects were not logged or were logged incorrectly.
- 4. Contrary to the QA Manual, Section 3.6 and Criterion V of Appendix B to 10 CFR Part 50, independent verification of vendor test results has not been performed for the last four months.

C. UNRESOLVED ITEMS:

None

D. STATUS OF PREVIOUS INSPECTION FINDINGS:

- 1. (Closed) Nonconformance (81-01); A method of design change verification was used which was not described in Quality System Requirements. The forms used have been modified to remove the method in question. The design control procedure will be revised to reflect this change. A review of verification activities found no further problems.
- 2. (Closed) Nonconformance (81-01): Inspection Control Tags did not have the latest revision of applicable drawings and initials of personnel. Instruction classes were held for personnel. A review of Inspection Control Tags found no further problems in this specific area, however, another nonconformance was identified in this area.
- (Closed) Nonconformance (81-01): A change to a drawing in use was not properly documented. Instruction classes were held for personnel. A review of drawings found in use in the shop found no further problems.

ORGANIZATION:

WESTINGHOUSE ELECTRIC CORPORATION, INSTRUMENTATION DEPARTMENT

HUNT VALLEY, MARYLAND

R PORT NO.: 99900217/81-02

INSPECTION RESULTS:

PAGE 3 of 3

E. OTHER FINIDNGS OR COMMENTS:

- 1. Nonconformances and Corrective Action The Material Review Board (MRB) activities for the past six months was reviewed. This included 21 reports. The review, disposition, and documentation of nonconformances followed procedures. Corrective action was documented for internal activities, however, a nonconformance was identified in this area regarding vendor corrective action. During this timeframe eight Material Rejection Notices had been dispositioned by MRB with vendor CARs. Defects and quality trends were summarized and reported. Weekly Defect Summary and Inspection Submittal and Discrepancy Records were reviewed. Hardware in the shop was reviewed for proper identification of defects. One nonconformance was identified in this area.
- Calibration Sixteen instruments and 10 crimping tools were inspected. Instruments and tools were found to be labeled properly. Records and procedures were found which established the acceptance limits, schedules, and results of calibration.
- 3. Procurement Controls The purchase order for three components for the Solid State Protection Systems were reviewed in detail. Cabinets, relays, and power supplies were the items on these purchase orders. The use of the Approved Vendor List, vendor evaluation and history was verified to follow the approved procedures. Vendor history files which include Survey Reports, Audit Checklists, Source Reports, Vendor Quality Rating System, Detail Reports, Questionable Vendor Reports, and Certified Vendors Reports were inspected. In this area one nonconformance was identified. An open item for follow up during a later inspection was also identified. The vendor certification and test data could not be found for some Class 1E power supplies on purchase order O2D-ASP 87737 which were inspected on April 25, 1981.

PERSONS CONTACTED

Occket/Report No. 31-02

Inspector Mchile

Page 1 of 3

MAME(Please Print)	TITLE(Please Print)	ORGANIZATION B sess Print
D.O. CIFORD	QA ENG	(W) INS. DEPT
H. L. ANSL	PROJ. ENG	New profession and the second
FF HEINS	GEN. MGR.	
R.W. LEE	PROD ASSURANCE	Presidential Control
J.M. BICK	PROSEMM MGR.	
D. M. WILSON	QA. ENG.	
B. E. EBANGN	QC SUPER	
D. E. FULLEN	1	Parameter and the parameter an
WE GARDNER	CAL, HAB LORR	
D. C. STEVENS	CAL LAB SUPER.	
3. LITON	Q ENG.	
J.G. BRASCH	PaEng	
L.L. HUGHES	PQA Ren-	
W. PATALON	ENG My.	
		Trice and the second second
一一一一大学大学		
The Windshift Bridge States		
r jeste de de		

Inspector Mahill

Scope/Hodule

DOCUMENTS EXAMINED

Bocket No. 99900 217 Report No. 81. 31-01 Page 2 of

		ı	
		ì	
		١	
		1	
		1	
		1	
		l	
		1	

-21	~ W vacuru	Evinion Min Prox	3/6/6 18/6/6 18/02/8 18/02/8 18/02/8	- 10 1 1 1 1 1 1 X
6. 6. 6. 6. 7. 7. 9. 7. 9. 7. 9. 7. 9. 7. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9. 9.	m m m m m m o	Non comforming Metinial Feature action The duet Devect Reporting System Tild Inoulde Esconds-System Spanned Ording on field remork 18580, 8810, 18881 EPSD 14 mst Volley Collination System Manuel CALIFEATION & CONTROL OF CRIMO TOOLS STANDARDS USED FOR CALIFFAMION	3-1-19 3-1-79 7-20-79	

Document Types:

- Drawing Specification

 - Procedure QA Manuai

- Purchas Order Internal Memo
- Other (Specify-If necessary)

- Columns:

- Sequential Item Mumber
 Type of Document
 Date of Document
 Revision (If applicable)

0518'811 1	- 62-22-9	3-1-79 7-44-79 8-1-79	18/9/6	04/13/8/	
TITLE/SUBJECT	Seu	July Faling System	to 4 % for 20 Califusts	e of Problematic Vendor (its	
Approuved.	2-Trek	Tutuples Su Vendor S Vendor S	P.O. 2377/16	Questionable	
2	on	m m m m	MUS	9	
	3.1	NETU	3.6		

- Procedure QA Manual
- Document Types:
 1. Drawing
 2. Specification
- Purchas Order Internal Memo
- Other (Specify-if necessary)

- Columns:
- Sequential Item Number
 Type of Document
 Date of Document
 Revision (If applicable)