

APPENDIX A

NOTICE OF VIOLATION

Duke Power Company
McGuire 2

Docket No. 50-370
License No. CPPR-84

As a result of the inspection conducted on September 15-18, 1981, and in accordance with the Interim Enforcement Policy, 45 FR 66754 (October 7, 1980), the following violation was identified.

10 CFR 50, Appendix B, Criterion XIII, as implemented by Duke Power Company QA Topical Report, Section 17.1.13, requires measures shall be established to control ... preservation of material and equipment in accordance with work and inspections to prevent damage or deterioration.

Contrary to the above, measures shall be established to prevent damage to installed cables at cable tray node point 12453 two Class IE blue cables were crushed flat by employees walking in the tray. This tray section is being used as a walkway. There is no procedure issued to control the use of cable tray as a walkway.

This is a Severity Level V Violation (Supplement II.E).

Pursuant to the provisions of 10 CFR 2.201, you are hereby required to submit to this office within thirty days of the date of this Notice, a written statement or explanation in reply, including: (1) admission or denial of the alleged violation; (2) the reasons for the violation if admitted; (3) the corrective steps which have been taken and the results achieved; (4) corrective steps which will be taken to avoid further violations; and (5) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown. Under the authority of Section 182 of the Atomic Energy Act of 1954, as amended, this response shall be submitted under oath or affirmation.

The responses directed by this Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Date: _____