
LICENSEE EVENT REPORT



LER ATTACHMENT - RO #2-81-135

Facility: BSEP Unit No. 2 Event Date: 12-16-81

As a result of an event involving this instrumentation on Unit No. 1, as reported in LER 1-81-07 and a post-TMI requirement, a plant modification package (1-80-78 for Unit No. 1 and 2-80-99 for Unit No. 2) has been developed. This modification will install a condensing pot in the reference leg in order to increase the accuracy and reliability of this instrument, and remove the requirement to have flow in the reference leg to ensure that it is full.