

PILGRIM NUCLEAR POWER STATION
RFD #1 ROCKY HILL ROAD
PLYMOUTH, MASSACHUSETTS 02360

R. D. MACHON
NUCLEAR OPERATIONS MANAGER
PILGRIM STATION

January 22, 1982

BECo Ltr. #82-17



Director, Region I
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Licensee Event Report 81-054/01T-5 (UPDATE REPORT)

Docket Number 50-293
License DPR-35

Gentlemen:

The attached Licensee Event Report 81-054/01T-5 "Masonry Wall Design" is hereby submitted in accordance with the requirements of Pilgrim Nuclear Power Station Technical Specification 6.9.B.1.i.

For future block walls identified during Refuel V as being unstable, notification and available information will be verbally transmitted immediately to the on-site NRC Inspector. If the on-site Inspector is not available, the Region I Section Chief for Pilgrim Nuclear Power Station will be notified.

An update to LER 81-054/01T will be issued within fourteen (14) days of above verbal notification. This fourteen (14) day report will include a complete report on the most recently identified unstable block wall, information previously issued on other unstable block walls and a progress report of construction efforts to repair these walls.

If there are any questions on this subject, please contact us.

Respectfully submitted,

A handwritten signature in cursive script, appearing to read "Charles J. Machon".

R. D. Machon
Nuclear Operations Manager
Pilgrim Station

MTM:ep

Enclosure: LER 81-054/01T-5

cc: Document Control Desk
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

8202020419 820122
PDR ADOCK 05000293
S PDR

IE22
3/11